AMENDMENT UNDER 37 C.F.R. § 1.111 USSN 10/042,321 Attorney Docket No. Q68046

## **IN THE SPECIFICATION:**

AI

At page 8, please replace the first full paragraph with the following new paragraph:

Fig. 3 is a cross-sectional view taken along the line 3-3 A-A of Fig. 2.

At page 8, please replace the third full paragraph with the following new paragraph:

Fig. 5 is a cross-sectional view taken along the line <u>5-5</u> B-B of Fig. 4.

At page 8, please replace the eighth full paragraph with the following new paragraph:

Figs. 10A, 10B, and 10C are plan views Fig. 10 is a plan view showing related lamp sockets having wrong attachment prevention ribs.

## At page 9, please replace the first full paragraph with the following new paragraph:

Fig. 1 is an exploded, perspective view showing one preferred embodiment of the lamp socket of the invention, Fig. 1 is a perspective view of the lamp socket of Fig. 1, Fig. 3 is a cross-sectional view taken along the line 3-3 A-A of Fig. 2, Fig. 4 is a plan view of a wire connection

AMENDMENT UNDER 37 C.F.R. § 1.111 USSN 10/042,321 Attorney Docket No. Q68046

24

portion of fig. 2, Fig. 5 is a cross-sectional view taken along the line <u>5-5</u> <del>B-B</del> of Fig. 4, and Fig. 6 is a plan view showing one preferred embodiment of the socket assembly of the invention.